

Selecting between Celsius and Fahrenheit in Flat Heat Press

- 1- Turn on Heat Press
- 2- Press both arrow keys ▲▼ at the same time for 5 seconds
- 3- Press up arrow ▲ until 88 is displayed
- 4- Press set button 4 times until CF appear on top display
- 5- Bottom display will show either 0 or 1. (Zero is Celsius and 1 is Fahrenheit, use arrow keys ▲▼ to change to your preference.)
- 6- Press set button 4 times to return to main display