



FASTFRAMES

EMBROIDER WHERE YOU HAVE NEVER EMBROIDERED BEFORE


Instructions for embroidering with the Single Frame Hat Hoop



Cut a piece of adhesive backing large enough to cover the sewing field. Place the backing on the underside of the frame sticky side up.



Loosen the 2 knobs and place the bill of the hat under the bill clamp.



Use the middle slot of the bill clamp and the pin on top to center your hat.



Once you have aligned the cap tighten your 2 knobs.